





Installation Guide



MOB




MOF



STORAGE



MOB



MOF



Electric drill

Drill bit
(Φ 8 & 5)

Tape measure
(3m-5m)



Silicone






Pencil



Screwdriver

Tools required for installation



CABINET



4B

4C

1D



2E



2F



2G

