




INSTRUCTION

RK-SCKD







Spirit level





Tape measure
(3m~5m)



Screwdriver



Hammer




Electric drill




Drill bit
(Ø8)



Pencil




Silicone




H1

16*




H2

16*




H3

16*




H4

28*φ8*30




H5

24*φ4*16




H6

4*




H7

5*Ø4x28



H8



6*Ø4x50






H9


6*Ø8x40



Stand-by Spareparts

 H1 2x	 H2 2x
 H5 2x	









REGLAGES DES PORTES

