



Installation Guide




MOB




MOF


1




4



STORAGE



MOB



MOF



Electric drill



Drill bit
(Φ 8 Φ 5)



Tape measure
(3m~5m)



Silicone




Pencil




Screwdriver

Tools required for installation


2




5



1



2



CABINET



4B




2E



4C



2F




1D




2G


3



6



7



3

